

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016569**Date Inspected:** 03-Sep-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhu Zhong Hai.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG components.**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS)

Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG Trial Assembly Yard:

This QA Inspector observed the following work in progress:

OBG Seg 10BW and Seg 10CW:

The Shielded Metal Arc Welding (SMAW) process on weld joint no: BP049-001-020 to 030. The welder is identified as 041713 and was observed welding in the 3G position. ZPMC Quality Control (QC) was identified as Wang Zhu. The welding variables recorded by QC appeared to comply with WPS: B-T-2213-B-U2-FCM-1.

The Flux Cored Arc Welding (FCAW) process on weld joint no's: OBW10C-001 and 002. The welders are identified as 202384, 040759 and 040609 and were observed welding in the 3G position. ZPMC QC was identified as Wang Zhu. The welding variables recorded by QC appeared to comply with WPS: B-T-2233-T.

The FCAW process on weld joint no: OBW10A-002. The welder is identified as 053316 and was observed welding in the 1G position. ZPMC QC was identified as Shi Lei. The welding variables recorded by QC appeared

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

to comply with WPS: B-T-223(2)1T-T.

The Submerged Arc Welding (SAW) process on weld joint no: OBW10A-003. The welders are identified as 042195 and 202756 and were observed welding in the 1G position. ZPMC QC was identified as Shi Lei. The welding variables recorded by QC appeared to comply with WPS: B-T-223(2)1T-T. See attached photo for further details.

OBG Seg 10BW:

The SMAW process on weld joint no: SEG063A-028. The welder is identified as 040656 and was observed welding in the 4G position. ZPMC QC was identified as Shi Lei. The welding variables recorded by QC appeared to comply with WPS: B-P-2214-TC-U4b-FCM-1.

OBG Seg 10AE and Seg 10BE:

The FCAW process on weld joint no's: EP151-001-018 and 020. The welder is identified as 040367 and was observed welding in the 4F position. ZPMC QC was identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with WPS: B-P-2114-FCM-1.

The FCAW process on weld joint no's: SP695-001-051 and 052. The welder is identified as 040367 and was observed welding in the 2F position. ZPMC QC was identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with WPS: B-T-2132.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Materials for your project.

Inspected By: Wadkar,Sailesh

Quality Assurance Inspector

Reviewed By: Peterson,Art

QA Reviewer